

O2 HE DI China_Suning

90x127mm

连接

您需要将空气净化器AC4556与应用程序连接以控制净化器并检测空气质量。下载并安装

在意空气

打开应用程序，点击“连接净化器或监测器”连接装置。
请按照应用程序中的步骤操作。

控件

电源

灯光
开关

自动
模式

风扇
速度

过滤网
重置

- 智能净化模式
- 智能去污染原模式
- 智能去气态污染物模式
- 智能去过敏原模式

- 睡眠模式
- 速度1-2
- 劲速

显示

睡眠模式

速度 1

速度 2

劲速

童锁

WiFi
指示灯

过滤网更换
提醒

预过滤网清洁
提醒

Gas

IAI

PM2.5

888

空气质量
指示灯

气态污染物
读数

室内过敏原
指数

PM2.5
显示

3 位数字显示屏
PM2.5/Gas/IAI

空气质量
指示灯

气态污染物读数从L1到L4，L1表示空气质量最佳

过敏原指数从1到12，其中1表示空气质量最佳

良好

一般

较差

非常差

维护

1

Gas IAI PM2.5

888

2

预过滤网

3

纳米级劲护滤网 专业S3型

当显示屏显示 F0 时

F0

需要清洁预过滤网

当显示屏显示 A3 时

A3

需要更换纳米级劲护滤网 专业S3型

! 在清洁或更换配件后按 3 秒重置该配件。

滤网使用一段时间后可能会散发异味，这是因为吸附了室内的气味导致。建议您将滤网置于阳光底下晾晒后继续使用。如晾晒后异味仍较明显影响使用体验，建议更换滤网。

4241 211 02942-1

O2 HE DI China_Suning

90x127mm

Connectivity



You need to connect your air purifier AC4556 with the App to control the purifier and check air quality. Download and install

Air Matters App

Open the app and click 'Connect an Air Purifier or Monitor' to connect your device. Please follow the steps in the app.

Control

Power
 Light on/off
 Auto mode
 Fan speed
 Filter reset

- Auto general mode
- Auto pollution mode
- Auto gas mode
- Auto allergen mode

- Sleep
- Speed 1-2
- Turbo

Display

Sleep mode
 Speed 1
 Speed 2
 Turbo speed

Child lock
 WiFi indicator
 Replace filter alert
 Clean pre-filter alert

Gas IAI PM2.5 888

Gas indicator

Indoor allergen index

PM2.5 indicator

3-digit display PM2.5 / Gas / IAI


Air quality ring

Gas index from L1-L4, L1 indicates best air quality

Allergen index 1-12, 1 indicates best air quality


Good
 Fair
 Poor
 Very poor

Maintenance




Pre-filter
 NanoProtect filter Pro S3

When display shows F0

•Time to clean the pre-filter

When display shows A3

•Time to replace NanoProtect filter Pro S3

! Press for 3 seconds to reset after cleaning or replacing accessory

The filter may produce smell after being used for a while because of the absorption of indoor air. Remove the filter and place it where it has direct sunlight and ventilation for several hours. Re-install and try using it again. If the odor remains, please replace the filter.

4241 211 02942-2